


SSK-HUD-RTX HASP HL driver 7.80 installation fails.

Problem

When installing the HASP HL driver **V7.80** (for the SSK-HUD-RTX - MassCore authorization dongle), the installation fails with the error message "Error when starting the Sentinel License Manager with parameters 1232 0.0 ..."



Solution

Please download and install the previous HASP HL driver version **7.63** from our website : https://download.merging.com/beta/AssociatedTools/Sentinel_LDK_Run-time_setup7.63.zip

Please reboot your computer after the install.